



Re-usable Nylon Coveralls

Protection Against Paint Sprays & Industrial Dirt & Grime

Protection

Nylon coveralls offer protection against paint sprays, fine particles and industrial dirt and grime.

Feature & Benefits


- Comfortable hood with excellent head room and drawstrings for secure face fit.
- Full body length dual zipper opens from top and bottom.
- Chest pocket and dual back pockets.
- Extra wide elasticated back keeps coveralls fitting snugly, reducing snags.
- Washable, durable and re-usable.
- Liquid resistant nylon material repels liquid sprays and splashes.

Common Areas of Use

- Panel beating, automotive spray painters, boat builders, mechanics, house painters, farmers, warehouse workers & cleaners.


Fabric Construction

- 190GSM nylon fabric, washable, durable & re-usable.



Understanding the Label



- All SureShield™ coveralls contain important information on the neck label which you should read before using the product. Below is a guide for interpreting the label.



- Coverall brand name
- Model identification
- CE Marking confirms Category III approval by INSPEC International Ltd (if applicable).
- Read this instruction sheet before use.
- Full body protection types (if applicable).
- Size
- Sizing pictogram showing body measurements.
- Care Instructions

Sizing

- Use the table below to determine the most appropriate size for you.



Information

Storage

- SureShield™ coveralls should be stored in dry areas away from direct sunlight.

Disposal

- SureShield™ coveralls can normally be disposed of in landfill or incinerated. Restrictions may apply depending on the contaminant encountered during use. Check with your local council for further details.

Warnings

- Where SureShield™ coveralls are used in conjunction with other PPE it may be necessary to tape cuffs to gloves, ankles to boots and hood to respiratory devices in order to achieve full "Type" protection. The user shall be the sole judge of correct combination of PPE and coveralls.
- Wearing coveralls, like many forms of PPE, can lead to heat stress. It is recommended that users adequately hydrate and take regular breaks to ensure dehydration and heat stress does not occur.
- When removing coveralls users should take care to avoid contamination by any hazardous substances encountered while wearing the coveralls. If coveralls are contaminated then standard decontamination procedures should be followed (i.e. decontamination shower).
- The user is responsible for ensuring the appropriate use of SureShield™ coveralls and no responsibility will be taken for improper use. Contact your SureShield™ provider for information about the correct product for your job.



Distributed by: